


MOOG
 STEERING & SUSPENSION

THE PROBLEM SOLVER®
**LOWER
MOUNTING
HARDWARE**

SELECT APPLICATIONS

PROBLEM:
**Rusted Or Stripped
Lower Strut Mounting Bolts**

Vehicle age and/or environmental conditions can cause the lower strut mounting bolts to be rusted and difficult to remove. During the removal process, the bolt heads may become stripped; the nut or bolt heads may become rounded. If this occurs, they will need to be replaced. This may slow down the repair job, as sourcing new hardware may be time-consuming.

In addition, while not required, installing new mounting hardware is recommended by many manufacturers when replacing ride control products.

SOLUTION:
**O.E. Equivalent Lower Mounting
Hardware Included**

Many MOOG® complete strut assemblies include lower mounting hardware such as strut mount bolts or pinch bolts.

This supplied hardware meets OE specification, and combined with the MOOG complete strut assembly, provides ease of installation and a thorough repair.


 LOWER STRUT
MOUNTING BOLTS


PINCH BOLT


 For parts lookup, visit www.FMe-cat.com | tech line: 1-800-325-8886

moogproblemsolver.com
